



- | | | |
|------|-------------|---|
| 1 | WS16-37 | |
| 2 | WS16-37 | |
| 3 | XWS16-59 | |
| 4 | U409135 | L |
| 5 | U409135 | R |
| 6 | UT4091 | L |
| 7 | U409135 | L |
| 8 | U409135 | R |
| 9 | XWS16-59 | |
| 10 | XU9078Z2 | |
| 11 | XU9078Z2-I | |
| 12 | XFWI78116B2 | |
| 13 | XU4078S2Z | |
| 14 | XUS6078-S | |
| 14.2 | 10000 | |
| 14.3 | 523706 | R |
| 15 | XUT6074GV82 | |
| 16 | XUK8078S2Z | |
| 16.1 | EX877LVV5E | |
| 17 | XU407846S2Z | |
| 18 | XFW7849B2 | R |
| 19 | XWB38-37 | |
| 20 | XWS38-37 | |
| 21 | GR2010A | L |
| 22 | XGML201 | |
| 23 | U6078S2Z | |
| 24 | XGML201 | |
| 25 | GR201OSZ2A | R |
| 25.2 | BI830CNB1 | |
| 26 | XGMC201 | |
| 27 | GR201178T2 | R |
| 28 | XWS38-37 | |
| 29 | FRD80-10051 | |
| 30 | 7550 | |
| 31 | ARG6063A | L |
| 32 | ARG606058 | |
| 33 | XWB38-37 | |

Anschlusswerte und Massangaben sind zwingend einzuhalten, um eine reibungslose Montage zu gewährleisten.



Möbel Dick GmbH
 Riedstrasse 1
 79787 Lauchringen
 Fachberater: ! S G alt, Telefon: +49 7741 68 33-35,
 Telefax: +49 7741 68 33-24, E-Mail: stefan.geng@kuechen-dick.de

Grundriss
 Kommission 16845/2

03.07.2024

Firma . Kojе 646 X2 UMA Achat/MOE Hava

..
 ..
 Telefon: .